





PRECISION SCALE WS260™

Quick Start Guide



1. Battery Level Indicator
2. Auto Power Off Indicator
3. Bluetooth Indicator
4. Measurement Value
5. Units

Enhance the **WS260**
With the Appion Central™ App



AppionTools.com

View Full
Product Manuals



Press	Menu, Select Menu Item	Backlight On/Off, Up Key	Down Key
Hold	Scale Power On/Off	Units Selection	Tare Scale
Both	↑ Bluetooth On/Off ↑		
	↑	Auto Power On/Off	↑

1. Quick PRESS a button for the “Press” function.
2. HOLD a button for 2 seconds for the “Hold” function.
3. Quick press BOTH buttons for the “Both” function.

Tare - Use to reset reading **and** account for load weight

Zero - Use to clear the reading **and** store the weight of an empty platform.



CAUTION: Refrigerant recovery cylinders can only be filled to 80% of the maximum capacity per DOT Regulations. Refer to page# 6 in the owners manual for additional information.

WARNING TO REDUCE THE RISK OF INJURY OR PRODUCT DAMAGE, READ OPERATION MANUAL PRIOR TO OPERATING PRODUCT.